

Certificate of Mailing

hereby certify that this correspondence is being deposited with the United States Postal Service as first class mail, postage prepaid in an envelope addressed to: Certificates of Correction Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450 on September 22, 2004.

Kurt A. Summe
Kurt A. Summe, Reg. No. 36,023

September 22, 2004

Date

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Patent No.: 6,744,312 *b2*
Issue Date: June 1, 2004
Applicant: White et al.
Application No: 10/090,857
Filed: March 5, 2002
Title: **ADAPTIVE POWER AMPLIFIER SYSTEM**
Art Unit: 2817
Confirmation No: 5898
Examiner: Steven J. Mottola
Atty. Docket No: ANCO-56US

Cincinnati, Ohio 45202

September 22, 2004

Certificates of Correction Branch
Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

**Certificate
SEP 30 2004
of Correction**

Sir:

**REQUEST FOR CERTIFICATE OF CORRECTION OF PATENT
FOR PTO MISTAKE (37 C.F.R. 1.322(a))**

Attached, in duplicate, is Form PTO-1050 (Substitute Form PTO76-22),
with at least one copy being suitable for printing.

The exact page and line number where the errors are shown correctly in
the application file are:

Column 6, line 45, reads "...to segment 222 and node A." and should read
– ...to segment 222-1 and node A. – as appears in the specification at page 14, line 5.

SEP 30 2004

Column 11, line 24, claim 19, reads "...of said parts by power amplifiers." and should read – ...of said ports by power amplifiers. – as appears in the specification at page 26, line 11.

Column 12, line 13, claim 25, reads "...wherein said muter routes said summed..." and should read – ...wherein said router routes said summed... – as appears in the specification at page 30, line 3.


Column 12, line 45, claim 31, reads "...configured for accepting a power..." and should read – configured for accepting a power... – as appears in the specification at page 33, line 3.

It is noted that errors appear in this patent of typographical nature or character, as more fully described above. It occurred in good faith. Correction thereof does not involve such changes in the patent as would constitute new matter or would require re-examination. A certificate of correction is requested. Please send the certificate to the undersigned.

If any other charges or credits are necessary to complete this communication, please apply them to Deposit Account 23-3000.

Respectfully submitted,

WOOD, HERRON & EVANS, L.L.P.



Kurt A. Summe, Reg. No. 36,023

2700 Carew Tower
441 Vine Street
Cincinnati Ohio 45202
(513) 241-2324 (phone)
(513) 241-6234 (facsimile)

SEP 30 2004

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,744,312 *B2*

Page 1 of 1

DATED : June 1, 2004

INVENTOR : White et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 6

Column 6, line 45, reads "...to segment 222 and node A." and should read – ...to segment 222-1 and node A. – as appears in the specification at page 14, line 5.

Column 11

Column 11, line 24, claim 19, reads "...of said parts by power amplifiers." and should read – ...of said ports by power amplifiers. – as appears in the specification at page 26, line 11.

Column 12

Column 12, line 13, claim 25, reads "...wherein said muter routes said summed..." and should read – ...wherein said router routes said summed... – as appears in the specification at page 30, line 3.

Column 12, line 45, claim 31, reads "...configured for accepting a power..." and should read – configured for accepting a power... – as appears in the specification at page 33, line 3.

MAILING ADDRESS OF SENDER:

WOOD, HERRON & EVANS, L.L.P.
2700 Carew Tower, 441 Vine Street
Cincinnati, Ohio 45202

PATENT NO. 6,744,312 *B2*

No. of add'l copies
@ 50¢ per page

Staple
Here
Only

Printer's
Trim
Line

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,744,312 *B2*

Page 1 of 1

DATED : June 1, 2004

INVENTOR : White et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 6

Column 6, line 45, reads "...to segment 222 and node A." and should read – ...to segment 222-1 and node A. – as appears in the specification at page 14, line 5.

Column 11

Column 11, line 24, claim 19, reads "...of said parts by power amplifiers." and should read – ...of said ports by power amplifiers. – as appears in the specification at page 26, line 11.

Column 12

Column 12, line 13, claim 25, reads "...wherein said muter routes said summed..." and should read – ...wherein said router routes said summed... – as appears in the specification at page 30, line 3.

Column 12, line 45, claim 31, reads "...configured for accepting a power..." and should read – configured for accepting a power... – as appears in the specification at page 33, line 3.

MAILING ADDRESS OF SENDER:

WOOD, HERRON & EVANS, L.L.P.
2700 Carew Tower, 441 Vine Street
Cincinnati, Ohio 45202

PATENT NO. 6,744,312 *B2*
No. of add'l copies
@ 50¢ per page